

SXT48S

QUICK INSTALLATION GUIDE



AUTO-TUNE PID TEMPERATURE CONTROLLER WITH CONTROL RELAY / SSR





GENERAL SPECIFICATION

- This device is designed for basic temperature control applications only in light industrial environments.
- PID temperature controller
- Auto-tuning for PID parameters
- Sensor type: T/C (J,K,T,S,R), Pt100, selectable, multi-input
- Selectable control type: P, PI, PD, PID or ON-OFF
- Ramp mode during power on
- "Anti-windup" in PID and PI mode
- Upper and Lower limit for SET setting
- Displays SET and PROCESS values
- Cold-junction compensation for T/C
- Line compensation for Pt100
- Excellent linearity with ºC/mV and ºC/Ohm look-up tables
- Input "Offset" feature
- Password protection
- High accuracy
- EEPROM memory to store settings
- Easy connection with plug-in connectors

WARNINGS

Installation and use of this device must be done by qualified, authorized and trained technical personnel only. Inspect device carefully before installation. Do not install and use broken and defective devices.

Do not disassemble device. Do not make any repair on any part of the device. There is no accessible part inside the device. Please contact to manufacturer for broken and defective devices.

Do not use device in environments subject to flammable, explosive and corrosive gases and/or substances.

This device is designed for applications only in light industrial environments. This device is not suitable for medical and residential use. This device is not suitable for use related with human health and safety. This device is not suitable for automotive, military and marine use.

Do not allow children and unauthorized people to use this device.

Before installation and any technical work, disconnect the power supply and mains connections.

Check the power supply voltage level before power on, and make sure voltage level is in specified limits.

Check quality of neutral line. Improper neutral line may give permanent damage to the device.

Connect an external power switch and an external fuse (1A, 250VAC) to the power supply line that are easily accessible for rapid intervention. Connect an external fuse (2A, 250VAC) for each relay output separately.

Use appropriate cables for power supply and mains connections. Apply safety regulations during installation. Install the device in a well ventilated place. Install the device permanently into a proper panel cut-out. Fix the device with two fasteners supplied with the device. Only front panel must be accessible after installation is completed. Do not operate the device other then the environmental conditions given in Technical Specification.

WIRING



WARNING: if 2 wire Pt100 is used, connect compensation lead to measuring lead: (**SXT48S: 10-11**)

Use correct compensation cables for T/C sensors.

Connect T/C cable directly to the device connectors.

Keep device, signal cables and communication cables away from circuit breakers, power cables and devices/cables emitting electrical noise.

Use shielded and twisted signal and communication cables and connect shield to earth ground on device side.

Keep length of signal and communication cables less than 3m.

Use insulated cable end-sleeves at the end of cables screwed to the device connector terminals.

TECHNICAL SPECIFICATIONS

[.] Dimensions	: 48x48mm
· Panel Cut-out	: 45,5x45,5mm
[.] Display	: 4 Digits 7 Segment (PV), 4 digits 7 Segment (SV)
[.] Sensor Type	: J,K,T,S,R type T/C, Pt100 selectable
[•] Measuring Scale	: -100600 °C, J type T/C (Inpt=J), -100.0 600.0 °C, J type T/C (Inpt=J.0)
	-1001300 °C, K type T/C (Inpt=k), -100.0999.9 °C, K type T/C, (Inpt=k.0)
	-100400 °C, T type T/C (Inpt=t), -100.0 400.0 °C, T type T/C (Inpt=t.0)
	01750 °C, S type T/C (Inpt=S) 0 1750 °C, R type T/C (Inpt=r)
	-100600 °C, Pt100, (Inpt=Pt) -100.0 600.0 °C, Pt100, (Inpt=Pt.0)
Resolution	$\pm 1 \text{ °C or } \pm 0.1 \text{ °C}$
· Accuracy	: ± 1 % (Over full scale)
[·] Control Form	: ON-OFF or P, PI, PD, PID - selectable
Control Output	: Relay (NO + NC), 250VAC, 2A, Resistive load / SSR (12Vdc, 20mA) - selectable
• Heat SET	: Lower Limit Upper Limit ^o C (H.Set)
[.] Heat Hysteresis	: 0 50 / 0.0 50.0 °C (H.Hys); PID is active if set to 0
[•] Alarm Hysteresis	: 1 50 / 0.1 50.0 °C (A.Hys)
Proportional Band	: 5 150 °C (Pb.C)
· Integral Time	: 0:00 30:00 min:sec. (OFF if set to 0:00)
[·] Derivative Time	: 0:00 10:00 min:sec. (OFF if set to 0:00)
[·] Control Period	: 1 200 sec. (Ct)
Offset	: -100+100 °C / -100.0 +100.0 °C (oFFS)
• Heating/Cooling	: Selectable (only ON-OFF control form is active for cooling)
[·] Cold. Junc. Comp.	: 0 50 °C (T/C)
[·] Line Comp.	: 10 Ohm max. (3 wire Pt100)
[·] Sensor Failure	: OUT output is active according to P.Err and Ct parameters in case of sensor
	failure, measurement out of range or hardware fails to measure input signal
a 1 1 1	(OUT output is OFF if P.err is 0).
· Supply Voltage	: 100240VAC, 50-60Hz
Power Consumption	
[•] Humidity	: < 70% (non-condensing)
· Altitude	: < 2000 m
· EMC	: EN 61000-6-1, EN 61000-6-3 (Only light industrial environment)
[.] Safety	: EN 61010-1; Pollution degree 1, measurement category I, (Only light industrial
. Ducto ation Class	environment, double/reinforced isolated, non-conductive pollution environment)
Protection Class	: IP20; according to EN 60529
• Temperature Spec.	: Operating: 0 50 °C, Storage -10°C 60°C (no icing)
' Weight	: < 0.5 kg
[.] Torque for screwing	. Max. 0.5 N.III



PROGRAMMING PARAMETERS



 When sensor type is changed, Up.L, Lo.L, H.Set, H.hys, oFFs may be set to a new value automatically, according to the selected sensor.
If sensor type is selected as Pt.0, J.0, K.0 or t.0. Error Messages: Fail: Sensor failure or sensor selection wrong E.FLS: Hardware failure E.CAL: Hardware failure E.EPr: Memory failure



DOWN UP BACK SET

PROGRAMMING HEAT SET



ON-OFF CONTROL

ON-OFF is active when "H.Hys" is other then 0



PID PARAMETERS

- P, PI, PD, PID is active when "H.Hys" is set to 0 (only for heating; h-C is set to "HEAt")
- PbC: Proportional band in °C.
- Ct: Control period for PID control. Prefer 4-10 sec.
- Ti: Integral time; Set in minutes. Determines how fast controller reacts to compensate the offset between SET point and the process value.

If set to 0, integral part is OFF. If set too low, process value may oscillate.

 - Td: Derivative time; Set in minutes. If set to 0, derivative part is OFF. Determines how sensitive the controller is to changes of the offset between SET point and the process value. If set too high, process value may oscilla te or overshoot.7



CLEANING

Do not use any solvents (alcohol, thinners, benzine, acid, etc.) or corrosive substances to clean the device. Use only a dry and clean non-abrasive cloth.

Before cleaning, disconnect the power supply and mains connections.

